

Polywater[®]

UPR[™] PR & NF “No Flow”

UTILITY POLE RESTORATION PRODUCTS



Polywater[®] UPR[™] Pole Repair products simplify repairing holes in wood utility poles caused by woodpeckers. The two-part formula mixes in the nozzle as it is injected into the damaged area. A partially used cartridge can be resealed and used again by attaching a new nozzle.

The UPR[™] resin and hardener are formulated to expand in the pole cavity to allow for quick and easy sealing, reducing labor hours. When UPR[™] expands in the hole, it fills irregularly shaped cavities for solid integration with the wood. This creates superior adhesion to the wood grain compared to other nonexpanding products.

Polywater[®] UPR[™] NF “No Flow” is a fast-reacting formula designed to thicken immediately. This prevents product from running out of small holes or cracks in the pole and getting on clothing or climbing gear. Both UPR[™] PR and NF harden similar to wood, making the repair gaffable.

UPR[®] PR and NF are packaged in kit form. Everything needed to repair damage to wood poles is included.

- No drilling to deploy product – Less labor time
- No mixing or direct handling of the product – Less mess
- No special deployment tools needed – Less expensive
- Single kit minimum order – Less stock
- Type PR kits include green-treated blocks – Less product needed

To fix one “football” sized hole on a pole, order UPR-PRKIT3 or UPR-NFKIT4. For multiple holes, transmission line jobs, or volume pricing order UPR-PRKIT12 or UPR-NFKIT12.

UPR™ PR & NF “No Flow” Utility Pole Restoration Products

Catalog Number	Description	Unit/Case
UPR-PRKIT3	Kit Contains: 3 UPR™ PR Pole Repair 250ml cartridges, 4 mixing nozzle, 5 green-treated wood blocks, 1 roll of stretch wrap, 1 pair of gloves, instructions.	1
UPR-PRKIT12	Kit Contains: 12 UPR™ PR Pole Repair 250ml cartridges, 16 mixing nozzles, 18 green-treated wood blocks, 1 roll of stretch wrap, 4 pairs of gloves, instructions.	1
UPR-NFKIT4	Kit Contains: 4 UPR™ NF Pole Repair 250ml cartridges, 6 mixing nozzles, 1 roll of stretch wrap, 1 pair of gloves, instructions.	1
UPR-NFKIT12	Kit Contains: 12 UPR™ NF Pole Repair 250ml cartridges, 18 mixing nozzles, 1 roll of stretch wrap, 3 pairs of gloves, instructions.	1
UPR-NF6B10	Kit Contains: 10 UPR™ NF Pole Repair 600ml side-by-side cartridges, 10 mixing nozzles, 1 roll of stretch wrap, 3 pairs of gloves, instructions.	1
MXR-30T-10	Mixing nozzle 10pk for UPR-PR kits	1
MXR-18T-10	Mixing nozzle 10pk for UPR-NF kits	1

To view technical information on our website go to:

Support Page: www.polywater.com/upr.asp

Application Videos: www.polywater.com/videos.asp



phone: 1-800-328-9384
1-651-430-2270
fax: 1-651-430-3634

email: support@polywater.com

11222 60th Street North, Stillwater, MN 55082, U.S.A.

ADHESIVES | CLEANERS | LUBRICANTS | **SEALANTS**

WWW.POLYWATER.COM

Important Notice: The statements here are made in good faith based on tests and observations we believe to be reliable. However, the completeness and accuracy of the information is not guaranteed. Before using, the end-user should conduct whatever evaluations are necessary to determine that the product is suitable for the intended use.

American Polywater expressly disclaims any implied warranties and conditions of merchantability and fitness for a particular purpose. American Polywater's only obligation shall be to replace such quantity of the product proven to be defective. Except for the replacement remedy, American Polywater shall not be liable for any loss, injury, or direct, indirect, or consequential damages resulting from product's use, regardless of the legal theory asserted.